POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

Summary Memorandum

Site ID: WA D009041450

County, Cowlitz

Priority Assessment: Medium

Backlog Red, Cat.:

Date/Revised:

1/22/85

Name and Location:

Weyerhaeuser Company Chlor-Alkali Plant 3000 Industrial Way Longview, WA 98632 Contact: Weyerhaeuser

Telephone: (206) 425-2150

Site Status: (X) Active () Inactive () Unknown

Site Description/TSD Activities:

The Weyerhaeuser Company operated a chlor-alkali plant which utilized the mercury cell process. Mercury-laden wastes were discharged into the Columbia River from 1956-70. After this, contaminated sludges were ponded in unlined pits which contaminated soils and potentially ground-water. WDOE supervised a cleanup of sludge ponds.

Waste Types/Quantities/Characteristics:

Approx. 93.5 lbs of mercury was lost from the chlor-alkali plant each day, Wastes contaminated with mercury and zinc were disposed of in sewers and directly into the Columbia River.

Physical/Social Environment:

Site overlies deep sandy loam and is located on the edge of the Columbia River. GW flow is towards the Columbia River; depth of GW is unknown. The chlor-alkali plant is located downstream in the same complex as a pulp mill and wood products plant owned by Weyerhaeuser. The site is located in an industrialized area.

Pollutant Mobilization/Pathways/Risk:

Soils, groundwater, and Columbia River sediments around the chlor-alkali site may be contaminated with mercury and zinc. The Columbia River acts as a barrier to contamination across the river to the north and pulls groundwater towards the river, eliminating concern for migration of contaminants to public drinking wells on either side.

Priority Assessment/Backlog Reduction Category:

Medium.

Followup Recommendations:

A complete sampling analysis of soils, groundwater, river sediments, and resident fish for mercury and zinc contamination should be affected in order to determine the extent of contamination at this site. If contamination is found to be extensive, this site may be considered for inclusion to the National Priority List.

USEPA SF

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT Part 1 - Site Information and Assessment

1. IDENTIFICATION
01 State 02 Site Number

0009041450

Fart	i i - Site ini	i Or ilia tio	n and	A >2622III	ent	WH	DOGAO	41450	
II. SITE NAME AND LOCA	TION								
01 Site Name (legal, common, or descript	live name of site)	_ ·	02 Street	, Route No.,	or Specific Loca	tion Identifier			
Weyerhaeuser-Chlor-	Alkali		3000) Indus	trial Way	y			
03 City				05 Zip Code		<u> </u>	07 County		
Longview			WA	98632	Cowlit	tz	O15	Dist O3	
09 Coordinates Lattitude Longi	tude			ownship/Ran			l	L	
			Sec.	31, T	BN, R2W,	WM			
46 07 46 1 10 Directions to Site (starting from neare	.22 59 24 est public road)								
-	·								
3 miles from city of off of Washington W	r Longvie: Jav	W,							
III. RESPONSIBLE PARTI					,				
01 Owner (if known)	<u> </u>		02 Street	(business m	ailing residenti	al)			
_			02 Street (business, mailing, residential)						
Weyerhaeuser Compar	. <u>y</u>				Headquart		,		
03 City Tacoma			1	l .	06 Telephone No		İ		
			WA	98407	(206)924	4234D	}		
07 Operator (if known and different from	owner)		08 Street	(business, π	nalling, resident	ial)			
Weyerhaeuser Compar	1V		3000) Indus	trial Way	,			
09 City	<u>'</u>		10 State	11 Zip Code	12 Telephone No	umber	l		
Longview			WA	98632	(206)425	52150			
13 Type of Ownership (check one)			I				<u> </u>		
(X) A. Private () B. Federa	ıl:			() C. State	() D. C	ounty () E	. Municipa	al	
() F. Other:				Û G. Unkr	• •	, () -			
14 Owner/Operator Notification on File (c	heck all that apply	<i>'</i>)		`					
(X) A. RCRA 3001, Date Rec'd: OE	3/ 18/80 ()	B. Uncontrol	led Waste	Site (CERCL	A 103c), Date Re	ec'd: /	/ ()C. None	
IV. CHARACTERIZATION			ZARD	-					
01 On Site Inspection	By (check all ti								
(X) Yes, Date: $70 - 476$					State ()	D. Other Cont	ractor		
() No	()E. Local H		() F	. Other:					
02 Site Status (check one)	Contractors Na		of Operat	ion					
(X) A. Active () B. Inactive	()C. Unknown			year ending	year () Unknown			
			15	956 Pr	es '				
04 Description of Substances Possibly Pro Potential contamination mercury and zinc.		_	er sed	diments	, and gro	oundwate	r wit	h	
					 				
05 Description of Potential Hazard to Envi	ronment and/or Po	pulation							
Chlor-Alkali plant uti discharged into the Co ponded in unlined pits	olumbia Ri	ver unt	til 19	970. A	fter this	y-laden s, sludg ly, grou	es we	re	
also. The sludge pond	ls were ex	cavate	l in a	a clean	up overse	een by W	DOE.		
. 1. 7					J		_		
V. PRIORITY ASSESSMEN		 							
01 Priority for Inspection (check one; if		checked, cor			·	D. Nama (5			
()A. High (inspection required promptly)	(X)B. Medium (inspection	required)		Low (inspect ailable basis)		D. None (no fu complete curr			
VI. INFORMATION AVAIL	ABLE FROM								
01 Contact	02 Of (agency/org	ganization)		·····			hone Numi		
Mike Gallagher	WDOE					(506) 4596	516	
04 Person Responsible for Assessment		06 Organizat		l l	phone Number	08 Date			
Suzanne Milham	WDOE	Rem. Ad	rt. D	iv. (20	6) 459641	7 01	/ 22 /	85	

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT Part 2 - Waste Information

1. IDENTIFICATION
01 State 02 Site Number

0009041450

					te mormat			WH	المر	03041400
	ASTE STATES, QU	JANTIT	IES	, AND C	HARACTER	ISTIC	CS			
01 Physica	al States all that apply)	02 Waste Q		ity at Site waste quantit		acteristi	cs (check all th	nat apply)		
()A.				waste quantiti ependent)	(x) A. Toxic		()E. Soluble	()		. Valadila
	Powder, Fines () F. Liquid	١			()B. Corre		() F. Infection			y Volatile
(x)c.		Tons: U					` '	` ,	J. Explo	
****	• •	Cubic Yar					()G. Flamma		K. React	
()p.	Other:	No. of Dru	ıms:	Unk.	(X)D. Persi	stent	() H. Ignitab		L. Incom	
		L		· · · ·		· · ·			M. Not A	(pplicable
	VASTE TYPE		_		02 11=14 =6					
Category	Substance Name		01 (Gross Amount	02 Unit of Measure	ļ	03 Cc	omments		
SLU	Sludge									
OLW	Oily Waste		L							
SOL	Solvents									
PSD	Pesticides					<u> </u>				
OCC	Other Organic Ch									
IOC	Inorganic Chemica	als	<u> </u>							
ACD	Acids									
BAS	Bases									
MES	Heavy Metals		9	93.5	lbs/dav	merc	curv. los	st to	rvr-	soils, swr
IV. H	AZARDOUS SUBST	ANCES			dix for mos	t fre	quently c	ted CA	Snur	nbers)
01 Cat.	02 Substance Name			CAS Number			sal Method			06 Measure of Concentration
MES	Mercury			439976	Sewer, p			Unkn		N/A
MES	Zinc			440666	charge			Unkn		N/A
MES	Magnesium			439954	charge	ITIC) LIVEL	Unkn		
MES	Barium			440393	_					N/A
11123	Baridii		- ′ ′	140393				Unkn	own	N/A
			⊢							
			ļ		· · · · · · · · · · · · · · · · · · ·					
								ļ		
			<u> </u>				- <u></u>	ļ		
							7.1			
		-	L							
	· · · · · · · · · · · · · · · · · · ·							<u> </u>		
					 		· ·- ·- ·	<u> </u>		
V. FE	EDSTOCKS (see A	ppendi	x fo	or CAS n	umbers		 			
Categor				02 CAS Numb			01 Feedsto	ck Name		02 CAS Number
FDS				1	FDS					
FDS				<u> </u>	FDS					
FDS		-		 	FDS					
FDS				 	FDS					
	OURCES OF INFOR	MATIO	N	cite spec	ific referen	CES	e a stat	e files	etc.	
				Cite spec	c referen	ces,	c.y., sta	e illes,	, etc.	'
WDQE	Industria sect	ion fi	lle	s.						
ייים ני	2UDO C:1									ļ
	SWRO Files	د		(M70						j
EPA Wa	ater discharge i	report	5]	7310						
1 ,	ver control of the co			•						j
										j
										I

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

1. IDENTIFICATION
01 State 02 Site Number

D009041450

Part 3 - Description of Hazardous Conditions & Incidents

II. HAZARDOUS CONDITIONS		
II. IIAZANDOOS CONDITIONS	AND INCIDENTS	
01 (X) A. Groundwater Contamination	02 () Observed (Date:)	(X) Potential () Alleged
	04 Narrative Description tes (sludge, liquid) were st Columbia River, rapid migra	
sand is expected to have	potentially contaminated gr e Columbia River, depth of g	oundwater. Ground- 11
01 (X) B. Surface Water Contamination	02 () Observed (Date: '56-'70)	() Potential () Alleged
	tall thow blant ment direct	
	.5 lbs/day Hg was lost from hing and there is a boat lau	
stream from the site.	ing and there is a boat lad	
01 (X) C. Contamination of Air	02 () Observed (Date:)	() Potential () Alleged
	04 Narrative Description haeuser site include those f	
	r-alkali plant itself doesn'	t contribute signi-
ficantly to air contamina	ation.	
01 (X) D. Fire/Explosive Conditions	02 () Observed (Date:)	() Potential () Alleged
03 Population Potentially Affected: No significant fire hazar	04 Narrative Description rd or explosion threat is in	dicated by local
		(V)
01 (X) E. Direct Contact 03 Population Potentially Affected:	02 () Observed (Date:) 04 Narrative Description	(X) Potential () Alleged
The Weyerhaeuser site is boat launch 1/4 mile dire	secured by fences, however	
DOSC ISCHICH INT HILL CITY	ectly compatherm thom the ar	· = .
DORU TRUNCH 174 MILE GIN	ectly downstream from the Si	ce.
01 (X) F. Contamination of Soil	02 (X) Observed (Date: '70-'76)	() Potential () Alleged
01 (X) F. Contamination of Soil 100 Ac 03 Area Potentially Affected (acres): Hg contamination of medi	02 (X) Observed (Date: '70-'76) Of Narrative Description um Sandy loam, well draining	() Potential () Alleged soils permeability
01(X)F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat	02 (X) Observed (Date: '70-'76) O4 Narrative Description um sandy loam, well draining ion from holding pond seepag	()Potential ()Alleged soils permeability e, contamination of
01(X)F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sec	02 (X) Observed (Date: '70-'76) Of Narrative Description um Sandy loam, well draining	()Potential ()Alleged soils permeability e, contamination of
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:)	()Potential ()Alleged soils permeability e, contamination of
01(X) F. Contamination of Soil 100 Acts 03 Area Potentially Affected (acres): Hig contamination of medical contamination of medical contamination of medical contamination contamination 10 (X) G. Drinking Water Contamination 10 (X) G. Drinking Water Contamination 10 Population Potentially Affected: 10 (C) The Columbia River channel	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description el protects drinking water o	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of
01 (X) F. Contamination of Soil 100 Ac. 103 Area Potentially Affected (acres): 106 Ac. 107 Ac. 108 Acres 109 Acres 100 Acre	02 (X) Observed (Date: '70-'76) Of Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient O2 () Observed (Date:) e1 Protects drinking water of izes a municipal water syste	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of
01 (X) F. Contamination of Soil 100 Ac. 103 Area Potentially Affected (acres): 106 Ac. 107 Ac. 108 Acres 109 Acres 100 Acre	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description el protects drinking water o	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of
01 (X) F. Contamination of Soil 100 Ac. 103 Area Potentially Affected (acres): 106 Ac. 107 Ac. 108 Acres 109 Acres 100 Acre	02 (X) Observed (Date: '70-'76) Of Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient O2 () Observed (Date:) e1 Protects drinking water of izes a municipal water syste	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination 03 Population Potentially Affected: The Columbia River channel the site. Longview util reservoir 3 miles north	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description el protects drinking water o izes a municipal water syste of the Chlor-Alkali plant.	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a
01 (X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01 (X) G. Drinking Water Contamination 03 Population Potentially Affected: The Columbia River channel the site. Longview util reservoir 3 miles north 01 (X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description el protects drinking water o izes a municipal water syste of the Chlor-Alkali plant.	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged I process. Present
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination Unknown The Columbia River channe the site. Longview util reservoir 3 miles north 01(X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no employees would not be e utilizes caustics and ot	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description izes a municipal water syste of the Chlor-Alkali plant. 02 () Observed (Date:)	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged I process. Present the present process
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hig contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination 03 Population Potentially Affected: The Columbia River channe the site. Longview util reservoir 3 miles north 01(X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no employees would not be e utilizes caustics and ot- by Labor and Industries.	O2 (X) Observed (Date: '70-'76) O4 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient O2 () Observed (Date:) O4 Narrative Description izes a municipal water syste of the Chlor-Alkali plant. O2 () Observed (Date:) O4 Narrative Description izes a municipal water syste of the Chlor-Alkali plant.	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged 1 process. Present the present process sterials regulated
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination Unknown The Columbia River channe the site. Longview util reservoir 3 miles north 01(X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no employees would not be e utilizes caustics and ot by Labor and Industries. 01(X) I. Population Exposure/Injury	02 (X) Observed (Date: '70-'76) 04 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient 02 () Observed (Date:) 04 Narrative Description izes a municipal water syste of the Chlor-Alkali plant. 02 () Observed (Date:) 04 Narrative Description izes a municipal water syste of the Chlor-Alkali plant.	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged 1 process. Present the present process sterials regulated (X) Potential () Alleged
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination 03 Population Potentially Affected: The Columbia River channed the site. Longview util reservoir 3 miles north 01(X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no employees would not be e utilizes caustics and other than of the columbia and industries. 01(X) I. Population Exposure/Injury 03 Population Potentially Affected: Unknown Any use of the Columbia	O2 (X) Observed (Date: '70-'76) O4 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient O2 () Observed (Date:) O4 Narrative Description izes a municipal water syste of the Chlor-Alkali plant. O2 () Observed (Date:) O4 Narrative Description longer uses the mercury cel xposed to mercury, although her potentially hazardous ma O2 () Observed (Date:) O4 Narrative Description longer uses the mercury cel xposed to mercury, although her potentially hazardous ma O2 () Observed (Date:) O4 Narrative Description River for fishing, swimming,	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged I process. Present the present process sterials regulated (X) Potential () Alleged etc. could lead to
01(X) F. Contamination of Soil 03 Area Potentially Affected (acres): Hg contamination of media >20"/minute. Contaminat river bottom sand and sectowards the river. 01(X) G. Drinking Water Contamination 03 Population Potentially Affected: The Columbia River channed the site. Longview util reservoir 3 miles north 01(X) H. Worker Exposure/Injury 03 Workers Potentially Affected: The Weyerhaeuser site no employees would not be e utilizes caustics and other than of the columbia and industries. 01(X) I. Population Exposure/Injury 03 Population Potentially Affected: Unknown Any use of the Columbia	O2 (X) Observed (Date: '70-'76) O4 Narrative Description um sandy loam, well draining ion from holding pond seepag diments. The slope gradient O2 () Observed (Date:) O4 Narrative Description el protects drinking water of izes a municipal water syste of the Chlor-Alkali plant. O2 () Observed (Date:) O4 Narrative Description longer uses the mercury cel xposed to mercury, although her potentially hazardous ma O2 () Observed (Date:) O4 Narrative Description River for fishing, swimming, n sediments. Fish eaten from	() Potential () Alleged soils permeability e, contamination of from the site is (X) Potential () Alleged on the south side of em supplied from a () Potential () Alleged I process. Present the present process sterials regulated (X) Potential () Alleged etc. could lead to

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTIFICATION
01 State 02 Site Number

Part 3 - Description of Hazardous Conditions & Incidents WA

D009041450

Tart 3 Description of Mazardous conditions o meldents was 10005041430
II. HAZARDOUS CONDITIONS AND INCIDENTS (continued)
01 (X) J. Damage to Flora 02 () Observed (Date:) () Potential () Alleged
04 Narrative Description Mercury discharges into the Columbia River may affect or be stored by plants growing in contaminated sediments and animal life.
01 (X) K. Damage to Fauna 02 () Observed (Date:) () Potential () Alleged
04 Narrative Description (include name[s] of species) See J above.
01 (X) L. Contamination of Food Chain 02 () Observed (Date:) (
01 (X)M. Unstable Containment of Wastes 02 () Observed (Date: 1970) () Potential () Alleged (spills/runoff/standing liquids/leaking drums) 03 Population Potentially Affected: 04 Narrative Description 1970 WDDE report: mercury sludges and other wastes stored in unlined pits scooped out of sandy river deposits. Observed seepage into ground.
01 (X) N. Damage to Offsite Property 02 () Observed (Date:) () Potential () Alleged
04 Narrative Description No record of damage to off-site property, potential exists for off-site contamination of any nearby wells and of river sediments.
01 (X) O. Contamination of Sewers, 02 (** Observed (Date: 56-70) () Potential () Alleged Storm Drains, WWTPs
Of Narrative Description Cooling water, condensate contaminated with mercury was released into sewer system. All mercury-contaminated waste streams were sewered prior to 1750: 1970
01 (X) P. Illegal/Unauthorized Dumping 02 (** Observed (Date: 56-70) () Potential () Alleged
O4 Narrative Description There are many documented violations of water discharge standards of excess mercury and zinc (SWRO, DDE inspection reports). Until 1970, there was no regulation of mercury or zinc usage or disposal at site.
05 Description of Any Other Known, Potential, or Alleged Hazards No other hazards known.
III. TOTAL POPULATION POTENTIALLY AFFECTED: Unknown
IV. COMMENTS
Although a cleanup of gross mercury contamination of holding ponds was completed in 1975-76, previous contamination of soils, groundwater, and Columbia River bottom sediments over a 20-year period warrant further investigation.
V. SOURCES OF INFORMATION (cite specific references: state files, reports, etc.)
NPDES No. 0000124 ; NPDES No. 0037672; WDOE/SWRO Files; WDOE Industrial Section Files, maps;



